

# Important Glorystar Switch Notice:

Our records indicate that you have recently purchased a Glorystar Christian Satellite System, which may contain an incorrectly labeled switch.

Due to manufacturing error the Ecodas 2x1 switch input ports are incorrectly labeled and will not properly switch between satellites when installed according to the Installation Guide.

To correct this error, simply reverse the coax cables connecting the LNBFs to the Switch.

Connect **LNBF #1** to Switch port **LNB 2 / 22KHz**

Connect **LNBF #2** to Switch port **LNB 1 / 0KHz**

**- OR -**

Do not install the switch. Assemble the dish with only one LNBF and connect directly to the satellite receiver without the 2x1 switch. This one LNBF solution will only result in the loss of three Glorystar channels:

- 1) CGN TV - Korean language
- 2) CBS - Korean language
- 3) TRWAM - Polish language

We apologize for any inconvenience that the incorrect label has caused! Please call our support team if you have any questions or require additional support. **866-597-0728 M - F, 7am - 4pm PT**

Thank you for your understanding!

