


REPLACEMENT PARTS NOT SHOWN

- V76-100 GEARMOTOR WITHOUT ARM
- V76-601 TIMING GEAR KIT
- V76-606 THRUST BEARING KIT
- V76-608 SCREW KIT

### TYPICAL WIRING CONFIGURATION



NOTES:  
 TOP & BOTTOM SWITCHES REFER TO HOW SWITCHES ARE ASSEMBLED TO MOTOR.  
 BOTTOM SWITCH DESIGNATES THE SWITCH CLOSEST TO THE CASTING.

### PERFORMANCE CURVE FOR V76-10

