

---

## Overview

Solo DVR 512 receivers have received updated software adding functionality to support a single satellite feed connection. Existing customers with an active 512 receiver will not be affected by this enhancement and will still be able to use the 512 as a dual tuner, single TV, SD DVR. The new functionality has been added to make the 512 a more versatile replacement option for older receivers that may be replaced by customers without a Technician visit.

---

## What Changed

- 512 software will support a single satellite feed connection to either Satellite In 1 or 2
  - Note: Existing customers with an active 512 receiver will receive the updated software, but their receiver's functionality will not change
- 512 receivers will be shipped to a customer's home to replace a defective 510 receiver
- Customers that are shipped a 512 receiver to replace a defective 510 will be able to connect the receiver with only Satellite In 1 or 2 and will not require a Technician Visit

The Solo DVR 512 may now be connected in any of these four configurations:

- Single satellite feed to Satellite In 1 using a Legacy, DP, or DPP feed
- Single satellite feed to Satellite In 2 using a Legacy, DP, or DPP feed
- Dual satellite feed with 2 cables from a Legacy, DP, or DPP feed
- Dual satellite feed with 1 cable from a DPP feed using a DPP separator

---

## Why It's Important

The 512 receiver will now function with a single satellite or dual satellite input.

- With a single satellite input connected to the 512, it will function as a single tuner, single TV, SD DVR
  - The user will be able to record one live program at a time, they may still watch a program recorded on the DVR while the live program is recording in the background
  - Users will only see check switch results for the input with a cable connected
- With a dual satellite input connected to the 512, it will function as a dual tuner, single TV, SD DVR
  - The user will be able to record one live program while simultaneously watching another live program
  - They may watch a third program that has been previously recorded on the DVR while recording two live programs in the background
  - Users will see check switch results indicating a connection for both inputs

---

## What I Need To Do

- The standard Technician installation for a 512 receiver is to connect with both Satellite In 1 and 2 connected
- Continue to install all 512 receivers in the dual feed configuration with both Satellite In 1 and 2 connected
- Be aware that you may encounter a 512 installed with only one satellite input. To bring these receivers up to the standard of a new 512 installation they must be reconfigured to a dual feed connection allowing use of both tuners